





1/6



1A



10



1B



2/6




FIG 2A






FIG 2B



54

Z	X	Y
0.000	0.375	0.375
0.050	0.317	0.317
0.100	0.260	0.260
0.150	0.219	0.219
0.200	0.195	0.195
0.250	0.188	0.188
0.300	0.188	0.187
0.350	0.189	0.186
0.400	0.191	0.185
0.450	0.194	0.182
0.500	0.198	0.179
0.550	0.202	0.176
0.600	0.208	0.172
0.650	0.214	0.168
0.700	0.221	0.163
0.750	0.228	0.157
0.800	0.237	0.152
0.850	0.247	0.146
0.900	0.257	0.139
0.950	0.269	0.133
1.000	0.282	0.126
1.050	0.296	0.119
1.100	0.311	0.112
1.150	0.327	0.104
1.200	0.343	0.098
1.250	0.358	0.092
1.300	0.373	0.086
1.350	0.388	0.081
1.400	0.401	0.076
1.450	0.415	0.072
1.500	0.427	0.068
1.550	0.439	0.064
1.600	0.449	0.061
1.650	0.459	0.059
1.700	0.467	0.056
1.750	0.474	0.054
1.800	0.480	0.052
1.850	0.484	0.051
1.900	0.487	0.050
1.950	0.489	0.050
2.000	0.551	0.113

4 / 6

44

2

4C

ETC